



Product group: Battery Tool
Bulletin No: 2021.02.00000004
Created on: 15/02/2021
Published: Internally¹ Distributors² Sales companies³ Dealers⁴ Service Centers⁵
Subject: M18SISM Software update

The latest software can be downloaded here:

https://d164iavpblhwri.cloudfront.net/M18SIC/MTCam_monitor_Softwareupdate.zip

download, unzip, and copy to a USB-Drive

Step 1

Open USB Cage:



Step 2

Enter USB-Drive into USB-A port:



¹ No communication outside TTI SBU's and EMEA

² Importers, distributors and service providers in a country (where there is no TTI SBU management)

³ SBU's


⁴ Network of customers who sell our tools in a country, managed by TTI SBU

⁵ Network of service center managed by a SBU




Step 3

Navigate to Settings:



Step 4

Go to System Update:



Step 5

Go to Wireless Monitor:






Step 6

Go to Update File:




Step 7

Confirm Software Update:



Step 8

Wireless Monitor is updating
(takes 2-5 minutes)





Step 9

Wireless Monitor Restarts after Update
is Complete

